Buffalo Guard Station, Residence (Bldg 1101) U.S. Highway 20/191 at Buffalo River Island Park Fremont County Idano

HABS No. ID-65-B

HABS ID, ZZ-ILPA, ZU-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Western Region
Department of the Interior
San Francisco, CA 94102

Form 10-920 (June 1983):

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE HISTORIC AMERICAN BUILDING SURVEY

HABS ID, 22-ILPA, 28-

ARCHITECTURAL DATA FORM

	LOCUMEN		I-am a manuar	
STATE	COUNTY		TOWN OR VICINITY	
Idaho	Fremon	<u>.</u>	Island Park	
HISTORIC NAME OF STRUCTURE (INC		NAME)		HABS NO.
Buffalo Guard Station Guard's				
(U.S.D.A., F.S., Targhee N.F. 7300 files)			ID-65-B	
SECONDARY OR COMMON NAMES OF	STRUCTURE			
D (11)		. ,		•
Building 1101				
COMPLETE ADDRESS (DESCRIBE LOC.	ATION FOR RURAL	SITES)		
U.S. Highway 20/191 at Buffa	1o Divon Tolon	l Domin Emanant C	annts Tlab	
DATE OF CONSTRUCTION (INCLUDE S		ARCHITECT(S) (INC.		
DATE OF CONSTRUCTION INTOLOGE	JOB NOL/	YIICHIY CO. (Of IMO		•
1936 (U.S.D.A., F.S., Targhet	e N.F. 7300 file	s) Unknown		•
SIGNIFICANCE (ARCHITECTURAL AN			OF STRUCTUR	E)
Constructed by the Civilian	Conservation Co	rns usino a stand	ard Forest	Service Region Four
plan (R4-53), but with log s:				
associated with the Federal				
STYLE (IF APPROPRIATE)	-			p. 2
Neo-Colonial				
MATERIAL OF CONSTRUCTION (INCL	UDE STRUCTURAL	SYSTEMS)		-
Wood frame on a concrete four		- · - · - · - · · - · ·	erior walls	were covered with
log siding, interior walls w	ith lath and pla	aster. Floors we	re wood.	
SHAPE AND DIMENSIONS OF STRUCT				
L-shaped (approximately square				
basement. Sketch and reprodu	uctions of stand	lard plans attach	<u>ed (ID-65-B</u>	-10 through 12).
EXTERIOR FEATURES OF NOTE				
"Shevlin" 2" X 8" log siding				
siding specified in the stand plan have been replaced with				
		. · -	steps (10-6	J-B-J and F).
INTERIOR FEATURES OF NOTE (DESC	CRIBE FLOOR PLAN	S, IF NOT SKETCHED)		
Kitchen, living room, bedroom				
The toilet, hall and closets				standard plan, with
an additional closet in the		as a stove (ID-65	-B-8).	
MAJOR ALTERATIONS AND ADDITIO	NS WITH DATES			
1966-1967: The shingle roof	was replaced w:	ith a metal roof	and the bed	room and living room
walls were panelled (ID-65-B-	-1 and 8).			
				
PRESENT CONDITION AND USE				
Last used as a year-round residence for Forest Service employees and in good to fair condition. In need of chimney and roof repair and new ceilings.				
orndition. In need of chimne		all and new celll	ngs.	
This documentation was compile		· ·	and the second s	•
and a Memorandum of Understan	nding with the A	Advisory Council	on Historic	Preservation.
POLIDOGO OF ANTONIA TION (MICE)	140 1107140 0411	TIONAL DECISES S	TATE ASSIST	OC STOL
SOURCES OF INFORMATION (INCLUD				
Included in Part III, attache				talo Ranger Station,
determined eligible for the	National Regist	er of Historic Pl	aces.	
COMPLED ACTULATION			T	DATE
COMPILER, AFFILIATION				DATE
James A. McDonald, Targhee N	.F.			10-18-84

Significance:

construction, but also locally unique because of the sidings. The residence originally served a seasonal Forest Guard engaged in fire suppression in the Island Park area.





